

J6802B-05

S E R V I C E N O T E

Supersedes:
NONE

J6802B - DNA MX

Serial Numbers: ALL

As of 1 April 2010, when replacing the PCMCIA adapter card(PN 0960-2378), a new Full Recovery Data CD is required for re-imaging the hard disk drive of the J6802B DNA MX.

Parts Required:

P/N	Description	Qty.
5067-4513	J6802B 6.60 Full Recovery Data Kit	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY	
AUTHOR: DM	PRODUCT LINE: 2J
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2010
PRINTED IN U.S.A.

April 6, 2010
Rev. 17



Situation:

A new driver is required for proper operation of the PCMCIA adapter.

Solution/Action:

Using the 6.60 Complete restore CD's install the correct drivers.