J6803A-02

<u>SERVICE NOTE</u>

Supersedes: None

J6803A DNA Pro

Serial Numbers: ALL

As of 16 April 2009, a new Full Recovery Data CD is required for re-imaging the hard disk drive of the J6803A.

Parts Required:

P/N Description Qty.

5012-3039 J6803A AND J6803B FULL 1
RECOVERY DATA CD
6.10.100.017

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: DM	PRODUCT LINE: 2J
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2009 PRINTED IN U.S.A.



April 20, 2009

Rev. 16

Page 2 of 2 J6803A-02

Situation:

Due to a change of support chips by the OEM vendor for the CPU card, PN 0960-2659, a new HDD image is required for proper operation of the J6803A.

Solution/Action:

Copies of the new image CD can be obtained from: http://gsdc.cos.agilent.com/mr/MR.asp