<u>J6803A-04</u> <u>S E R V I C E N O T E</u>

Supersedes: NONE

J6803A - DNA Pro

Serial Numbers: ALL


As of 1 April 2010, when replacing the PCMCIA adapter card (PN 0960-2378), a new Full Recovery Data CD is required for re-imaging the hard disk drive of the J6803A DNA Pro.

Parts Required:
P/NDescriptionQty.5067-4512J6803A And J6803B 6.60 Full Recovery Data Kit1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: DM	PRODUCT LINE: 2J
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2010 PRINTED IN U.S.A.





Situation:

A new driver is required for proper operation of the PCMCIA adapter.

Solution/Action:

Using the 6.60 Complete restore CD's install the correct drivers