

# J6803B-05

## S E R V I C E N O T E

Supersedes:  
NONE

### J6803B - DNA Pro

Serial Numbers: ALL

As of 1 April 2010, when replacing the PCMCIA adapter card (PN 0960-2378), a new Full Recovery Data CD is required for re-imaging the hard disk drive of the J6803B DNA Pro.

**Parts Required:**

P/N	Description	Qty.
5067-4512	J6803A And J6803B 6.60 Full Recovery Data Kit	1

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
<b>INFORMATION ONLY</b>	
AUTHOR: DM	PRODUCT LINE: 2J
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2010  
PRINTED IN U.S.A.

April 6, 2010

Rev. 17



**Agilent Technologies**

**Situation:**

A new driver is required for proper operation of the PCMCIA adapter.

**Solution/Action:**

Using the 6.60 Complete restore CD's install the correct drivers.