

M9045B-01

S E R V I C E N O T E

Supersedes:
NONE

M9045B PCIe ExpressCard Adapter

Serial Numbers: 000000-159999

Potentially slower communication due to M9045B bit error issue

Parts Required:

P/N	Description	Qty.
None		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
<input type="checkbox"/> Calibration Required	PRODUCT LINE: BL
<input checked="" type="checkbox"/> Calibration NOT Required	AUTHOR: TP
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2012
PRINTED IN U.S.A.

September 21, 2012

Rev. 20



Situation:

Affected M9045B described above configured with laptops that are sensitive to low output clock amplitude may experience occasional bit error that will cause the system communication to be slower.

Solution/Action:

The M9045B has been improved to have higher output clock amplitude. To avoid the bit error issue, upgrade to the new M9045B with serial number 160000 or greater.