

M9183A-01

Information Only Service Note

Supersedes:
NONE

M9183A PXI Digital Multimeter

Serial Numbers: ALL

The Problem – Reemphasize on safety precaution

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

ADMINISTRATIVE INFORMATION

<input type="checkbox"/> Calibration Required	PRODUCT LINE: GM
<input checked="" type="checkbox"/> Calibration NOT Required	AUTHOR: SH

ADDITIONAL INFORMATION:

Situation:

General safety precautions must be observed during all phases of operation.

Solution/Action:

Do not connect the V HI and V LO or I HI and I LO terminals to any test leads when the measurement function does not utilize these terminals. Disconnect any external device that is connected to the V HI and V LO or I HI and I LO terminals.

The instrument chassis and cover must be connected to an electrical ground to minimize shock hazard. The ground pin must be firmly connected to an electrical ground (safety ground) terminal at the power outlet.

Please refer to recommended usage method at [PXI Digital Multimeter Startup Guide](#)

Revision History:

Date	Service Note Revision	Author	Reason for Change
22 Jan 2021	01	Hashini	As Published