# MSO7034A-01 S E R V I C E N O T E

Supersedes: NONE

## MSO/DSO7000A Series InfiniiVision Oscilloscope

Serial Numbers: MY48250001 or below and SG48250001 or below

New Cap-Strap Handles are replacing older ones that might crack with use.

Part number 5041-9607 replaces part number 5042-6805.

**Parts Required:** 

P/N Description Qty.

5041-9607 Cap-Strap Handle 2

#### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	[x] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS  LABOR: 0.5 Hours	
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE [x] SERVICE CENTER [[]] CHANNEL PARTNER	SERVICE [[]] RETURN INVENTORY: [x] SCRAP [[]] SEE TEXT	USED [[]] RETURN PARTS: [x] SCRAP [[]] SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: (1-Jun-2010)	
AUTHOR: EG		PRODUCT LINE: PL1A	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2008 PRINTED IN U.S.A.



Page 1 of 2

September 30, 2008

Rev. 15

Page 2 of 2 MSO7034A-01

#### **Situation:**

Old Cap-Strap Handles (P/N 5042-6805) may crack.

### **Solution/Action:**

Replace with new Cap-Strap Handles, P/N 5041-9607.