N1911A-01 <u>S E R V I C E N O T E</u>

Supersedes: none

Agilent N1911A P-Series Peak Power Meter (Single Channel)

P-Series Power Meter Firmware Upgrade Utility

To Be Performed By: Agilent-Qualified Personnel or Customer

Firmware Revision	Firmware Upgrade Utility	Qty
P-Series Power Meter Firmware version A.03.01	P Series Firmware Upgrade Utility	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASS	BIFICATION:			
	MODIFICATION	RECO	MMEND	ED
ACTION CATEGORY:	[[]] IMMEDIATELY [[]] ON SPECIFIED FAILURE X AGREEABLE TIME	STANDARI	DS: LABOR: 0.5 Hou	ırs
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER	SERVICE INVENTORY:	[[]] RETURN [[]] SCRAP [[]] SEE TEXT	USED [[]] RETURN PARTS: [[]] SCRAP [[]] SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RES	SPONSIBLE UNTIL:	1 st April 2009 for All Warranty Units.
AUTHOR: Alvin Khoo	PRODUCT LINE: WC			•
ADDITIONAL INFORMA	TION:			
© AGILENT TECHNO	DLOGIES, INC. 2007		N. 4	

PRINTED IN U.S.A.



March 13, 2007

Page 2 of 4 Situation:

P Series Firmware Upgrade Utility, as shown in Figure 1, is used to upgrade P-Series power meter firmware version A.03.01 and above. If P Series Firmware Upgrade Utility is used to run any older version of firmware package, which downgrades P-Series power meter firmware version A.03.01 to any older versions, error will occur with a pop-up Error dialog box as shown in Figure 2.

Solution/Action:

To downgrade P-Series firmware version A.03.01 to an older version, the N191x_Firmware_Upgrade.txt file that resides in the folder of the older firmware version must be renamed to Firmware_Upgrade.txt.

🔀 P Series Fim	ware Upgrade Utility	
Release Directory Visa Instrument		Browse
	Upgrade]
<	× ≥	Close

Figure 1 P Series Firmware Upgrade Utility

Page 3 of 4



Conclusion

Users are unable to use N191x Firmware Upgrade Utility, as shown in figure 3, to upgrade P-Series power meter firmware version A.02.01 and above. Users must use P Series Firmware Upgrade Utility to perform the upgrading.

If users choose to downgrade their firmware version using the P Series Firmware Upgrade Utility, users must rename the N191x_Firmware_Upgrade.txt file to Firmware_Upgrade.txt.

je 4 of 4			
Release Directory			Browse
Visa Instrument		•	
Select Images to Upgrade Host DAP DSP DAP FPGA Front Panel Motherboard	Advanced Options Host Recovery Host BootROM DAP DSP BootROM DAP FPGA Recovery		
	Upgrade		
<		~	Close
)	Firmware Upgrade Utility		

Caution

- Do not dismantle the front panel.
- Do not touch the 1 mW reference.
- Once the front panel is dismantled or 1 mW is affected, service and calibration are needed.
- Information about verification of 1 mW is documented in service guide.