

N5181A-10

Information Only Service Note

Supersedes: None

N5181A MXG Analog Signal Generator

Serial Numbers: ALL

The Problem - The N5180-60110 Front Panel Replacement Kit is No Longer Available

Parts Required:

P/N Description Qty.

N5180-60266 Front Panel Replacement Parts Kit 1

Situation:

ADMINISTRATIVE INFORMATION

[[]] Calibration Required PRODUCT LINE: 15
X Calibration NOT Required AUTHOR: MM

ADDITIONAL INFORMATION:



New front panel LCDs for this instrument are no longer available, so the complete front panel replacement kit, part number N5180-60110, can no longer be provided. However, all the lower level parts will still be available for replacement in one form or another, if needed.

Solution/Action:

Table 1 shows all the lower level parts that were included in the discontinued N5180-60110 Front Panel Replacement kit, along with the current part numbers that can be used to order these parts.

Table 1 – Discontinued Front Panel Replacement Kit Contents – N5180-60110

Part Number	Qty	Description	Order As	
0950-4111	1	Backlight Inverter, 5-WATT 1-Output	N5180-60025	
1000-1515	1	Filter EMI Display 159.70X67.30X1.90-mm	N5180-60413 ¹	
1460-2022	1	Spring, Compression .18-in-OD .5-in-LG	N5180-60413 ¹	
2090-0908	1	Display LCD, 6.2-in 640X240-Pixels	N5180-69465	
5041-9170	2	Trim-FR FR Side 1 Each	5041-9170	
8121-1380	1	Cable-Assembly, Ribbon, LCD Control	8121-1380	
8121-1382	1	Cable-Assembly, Ribbon, Keypad Control	8121-1382	
8121-1383	1	Cable-Assembly, Harness, Power Switch	8121-1383	
8160-0660	1	RFI Round Strip Steel	8160-0660	
8160-1801	1	EMI-RFI Gasket Shielding 0.078-in-DIA	N5180-60266	
N1912-61002	1	Cable-Assembly, Backlight	N1912-61002	
N5180-00004	1	Shield, Inverter	N5180-60025	
N5180-20107	1	Front Frame	N5180-60266	
N5180-40002	1	Keypad, Main	N5180-60021	
N5180-63004	1	PCA, Front Panel Interface	N5180-60025	
N5180-80002	1	Overlay, Front Panel Keypad, Analog	N5180-60266	
N5180-80023	1	Overlay, Front Panel, Left Side	N5180-80023	
N5180-80027	1	Nameplate, N5181A 1 GHz	N5180-80027	
N5180-80028	1	Nameplate, N5181A 3 GHz	N5180-80028	
N5180-80029	1	Nameplate, N5181A 6 GHz	N5180-80029	
W1312-00032	1	Front Subpanel	N5180-60266	
W1312-40011	1	Display Boot	N5180-60266	
W1312-40012	1	Display Hold Down	N5180-60266	
W1312-40013	1	Keypad, Power Switch	N5180-60022	
W1312-40017	1	Knob, RPG Large	W1312-40017	
W1312-63013	1	PCA, USB	N5180-60023	
W1312-63017	1	PCA, Power Switch	N5180-60022	
W1312-63020	1	PCA, Keypad	N5180-60021	

¹ The N5180-60413 kit includes the parts listed along with others that were not designed for this instrument. Use the parts needed and discard the rest.

As can be seen in Table 1, a new front panel replacement parts kit has been created to provide the parts needed if the front frame casting itself needs to be replaced. This new kit replaces the discontinued N5180-60110 kit but will not include all the lower level parts that were in the previous kit. It will only contain the parts listed in Table 2. If any other parts are needed, they will need to be ordered separately, using the "Order As" part numbers shown in Table 1.

Table 2 – New Front Panel Replacement Parts Kit Contents – N5180-60266

Part Number	Qty	Description
8160-1801	1	EMI-RFI Gasket Shielding 0.078-in-DIA
N5180-20107	1	Front Frame
N5180-80001	1	Overlay, Main Keypad, Digital
N5180-80002	1	Overlay, Main Keypad, Analog
N5180-80011	1	Overlay, Nameplate, 20 GHz
N5180-80012	1	Overlay, Nameplate, 40 GHz
N5180-80013	1	Overlay, Main Keypad, Microwave
N5180-80014	1	Overlay, Nameplate, 32 GHz
N5180-80023	1	Overlay, Front Panel, Left Side
N5180-80025	1	Nameplate, N5182A 3 GHz
N5180-80026	1	Nameplate, N5182A 6 GHz
N5180-80027	1	Nameplate, N5181A 1 GHz
N5180-80028	1	Nameplate, N5181A 3 GHz
N5180-80029	1	Nameplate, N5181A 6 GHz
W1312-00032	1	Front Subpanel
W1312-40011	1	Display Boot
W1312-40012	1	Display Hold Down

The N5180-60266 Front Panel Replacement Parts kit will contain parts that will not be used or needed for all repairs. These parts can be discarded or used for future repairs on other instruments. The majority of these will be nameplates. Be sure to select the correct nameplate from the kit for the instrument model and frequency range being repaired.

Revision History:

Date	Service Note Revision	Author	Reason for Change	
29 Jul 2020	01	Mike Medley	As Published	
29 Jul 2020	UT	Mike Medley	AS Published	