

N5191A-01B

Modification Recommended Service Note

Supersedes: N5191A-01A

N5191A -UXG X-Series Agile Signal Generator

Serial Numbers: see list last page

The Problem – N5191A service notes are classified as technical data. Service notes related to this product are store on the US Domain / Share point folder

Parts Required:		
P/N	Description	Qty.
N5191-60153	Power supply	1

ADMINISTRATIVE INFORMATION

ACTION	[]]] ON SPECIFIED FAILURE	STANDARDS
CATEGORY:	[X] AGREEABLE TIME	LABOR: 1.0 Hours
LOCATION	X SERVICE CENTER	SERVICE: [[]] RETURN USED [[]] RETURN
CATEGORY:	[]] ON-SITE (active On-site contract required)	INVENTORY: [[]] SCRAP PARTS: [X] SCRAP
	[[]] CHANNEL PARTNERS	[[]] SEE TEXT [[]] SEE TEXT
AVAILABILITY	: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 07 January 2025
	[[]] Calibration Required	PRODUCT LINE: 15
	X Calibration NOT Required	AUTHOR: MW

ADDITIONAL INFORMATION:



Situation:

N5191A service note are classified as technical data. Service notes related to this product are store on the US Domain / Share point folder

Solution/Action:

- 1) obtain US Domain access
- 2) After obtaining US Domain log in and unique password
- 3) View N5191A Service notes at https://keysight.sharepoint.us/documents/servicenotes

Revision History:

Date	Service Note Revision	Author	Reason for Change
18 Sept 2018	01	SN	As Published
02 Oct 2018	02	SN	Add Contact division
07 Jan 2022	03	MW	Extend No Charge available to 07 Jan 2025