# Modification Recommended Service Note

Supersedes: NONE

# N5745A DC System Power Supply

Serial Numbers: Refer to Table 1

The Problem - Current programming and readback accuracy may marginally out of specification.

# Parts Required:

NONE

#### ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 1 Ho	our		
LOCATION CATEGORY:	[X] SERVICE CENTER [[]] ON-SITE (active On-site contract required) [[]] CHANNEL PARTNERS	SERVICE: [[]] RETU INVENTORY: [[]] SCR. [X] SEE	AP PARTS:	[[]] RETURN [[]] SCRAP [X] SEE TEXT	
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 8 <sup>th</sup> March 2025			
	[X] Calibration Required [[]] Calibration NOT Required	PRODUCT LINE: SP AUTHOR: LIM ZHAN N	ИING		

ADDITIONAL INFORMATION: No impact on service inventory Not applicable



# Situation:

For units listed in Table 1, the current programming and readback accuracy may marginally out of specification.

# Solution/Action:

Kindly contact Keysight Technologies Customer Contact Center at <a href="https://www.keysight.com/find/contactus">www.keysight.com/find/contactus</a> for sending the affected unit back to service center.

Service center to perform performance verification on current programming and readback accuracy.

If performance verification PASSES

No action needed

If performance verification FAILS

• Calibrate (adjustment) the unit

Table 1: Affected Serial Number

US22L3785R	US22M4528R	US23C5868R
US22M4512R	US22M4531R	US23F3701R
US22M4520R	US23C5862R	US23F3702R

# **Revision History:**

Date	Service Note Revision	Author	Reason for Change	
29 <sup>th</sup> Feb 2024	01	LIM ZHAN MING	As Published	