Modification Recommended Service Note

Supersedes: NONE

N5770A DC System Power Supply

Serial Numbers: Refer to Table 1

The Problem – Current programming and readback accuracy may marginally out of specification.

Parts Required:

NONE

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 1 Hour	
LOCATION CATEGORY:	[X] SERVICE CENTER [[]] ON-SITE (active On-site contract required) [[]] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: [[]] SCRAF	P
AVAILABILITY	': PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 8 th March 2025	
	[X] Calibration Required [[]] Calibration NOT Required	PRODUCT LINE: SP AUTHOR: LIM ZHAN MING	

ADDITIONAL INFORMATION: No impact on service inventory Not applicable



Situation:

For units listed in Table 1, the current programming and readback accuracy may marginally out of specification.

Solution/Action:

Kindly contact Keysight Technologies Customer Contact Center at www.keysight.com/find/contactus for sending the affected unit back to service center.

Service center to perform performance verification on current programming and readback accuracy.

If performance verification PASSES

No action needed

If performance verification FAILS

• Calibrate (adjustment) the unit

Table 1: Affected Serial Number

US22K1469R	US22K1469R
US23A0126R	US23A0126R

Revision History:

Date	Service Note Revision	Author	Reason for Change	
29 th Feb 2024	01	LIM ZHAN MING	As Published	