N7019A-01

Modification Recommended Service Note

Supersedes: NONE

N7019A USB Type-C ® Active Link Fixture

Serial Numbers: US59140101 - US59140183

The Problem – The N7019A can fail when used above 5V/3A.

Parts Required:

NONE

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[]] ON SPECIFIED FAILURE X AGREEABLE TIME	STANDARDS LABOR: 0.2 Hours	
LOCATION CATEGORY:	CUSTOMER INSTALLABLE ON-SITE (active On-site contract required) X SERVICE CENTER CHANNEL PARTNERS	INVENTORY: [[]] SCRAP PARTS: [[]] S	RETURN SCRAP SEE TEXT
AVAILABILITY	: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: June 10, 2023	
	[[]] Calibration Required X Calibration NOT Required	PRODUCT LINE: PL1A AUTHOR: MR	

ADDITIONAL INFORMATION:



Situation:

The product is specified to operate up to 20V/5A at Vbus input. However, it has been discovered that a component in the product is not rated for that voltage and will fail.

Solution/Action:

- o For affected products, use them only at 5V/3A until they are reworked.
- o Keysight has a rework to solve this problem. The N7019A must be returned to the factory for this rework. Customers must contact their Keysight Sales Representative to arrange for the return of the product for the rework. Units with serial #'s listed above will be reworked and returned directly to customers as soon as possible.
- The affected products can also be identified by the regulatory label located on the bottom of the product. If the label looks like that below, the product has the reliability issue:



If the label looks like this one below, where the UKCA mark is added, the product does not have the reliability issue (it has already been reworked or was built new):



Revision History:

Date	Service Note Revision	Author	Reason for Change
06 Jun 2022	01	Mark Rowley	As Published
	·		