

N9322C-01

Information Only Service Note

Supersedes:
NONE

N9322C – RF Spectrum Analyzer

Serial Numbers: " CN0743A723 / CN0743A882"
Manufacturing ID Number: NONE

Keyboard Responsive Issue

Parts Required:

P/N	Description	Qty.
N9322-63002	Key Board Assembly	1

Situation:

After boot up and normally work for a while, N9322C's keyboard will have no response, or response very slow.

ADMINISTRATIVE INFORMATION

<input type="checkbox"/> Calibration Required	PRODUCT LINE: CM
X Calibration NOT Required	AUTHOR: Xingsa Li

ADDITIONAL INFORMATION:

Solution/Action:

Replace the N9322C's keyboard assembly N9322-63002 to fix this issue.

Revision History:

Date	Service Note Revision	Author	Reason for Change
19 Oct. 2017	01	Xingsa Li	As Published