

N9912A-06A

S E R V I C E N O T E

Supersedes:
N9912A-06

N9912A - FieldFox RF Analyzer

Serial Numbers: MY50490001-MY50499999

New I/O Parts Due to FieldFox System Board Change

Parts Required:

P/N	Description	Qty.
NONE		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY	
AUTHOR: DYCS	PRODUCT LINE: WN
ADDITIONAL INFORMATION: This service note only address unit with serial prefix MY5049.	

© AGILENT TECHNOLOGIES, INC. 2012
PRINTED IN U.S.A.

February 28, 2012

Rev. 19



Agilent Technologies

Situation:

The FieldFox system board has been replaced with a new version with better reliability and ROHS compliance. The new system board is equipped with a micro-SD card reader, replacing the old mini-SD card reader.

Old I/O input with mini-SD card reader



New I/O input with micro-SD card reader.

**Solution/Action:**

When performing replacement, the System Board Kit (N9912-60032) comes with a system board, gasket and all the required I/O panel overlays.

The replacement procedure is found in the Service Guide, N9912-90003. Please refer to the Chapter 7 section titled, "Removing and Replacing the Case Group Parts."