Modification Recommended Service Note

Supersedes: NONE

N9937B FieldFox Handheld Microwave Spectrum Analyzer, 18 GHz

Serial Numbers: MY59221067, MY59221082, MY59221212

The Problem - The battery may go into Sleep mode after a short period of inactivity. Refer to www.keysight.com and the Contact Keysight link.

Parts Required:

P/N Description Qty.

Battery-Rechargeable Li-Ion 10.8V 6400mAh 1420-0937 1pc

ADMINISTRATIVE INFORMATION

ACTION		STANDARDS		
CATEGORY:	TEGORY: X AGREEABLE TIME LABOR: 0.5 Hours			
LOCATION CATEGORY:	X SERVICE CENTER	SERVICE: USED INVENTORY: X SCRAP PARTS: X SCRAP		
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 30-June-2022		
	X Calibration NOT Required	PRODUCT LINE: PLWN AUTHOR: JY		

Affects: N9913/4/5/6/7/8B and N9933/4/5/6/7/8B



Situation:

The battery may go into Sleep mode after a short period of inactivity. Battery replacement needed. Solution/Action:

1. Open the battery door and remove the battery from Fieldfox unit.



- 2. Check the serial number of the battery. Refer to the serial number list below.
- 3. If the battery serial number match the list of serial number below. Please order a new replacement battery (P/N: 1420-0937) from stock. Properly scrap the used battery.

If the battery serial number not in the list below. No replacement needed.

If the Fieldfox unit doesn't come with a battery. No replacement needed.



If you have any questions about this process, please contact: Christopher Rich christopher_rich@keysight.com

Christopher Rich christopher_rich@keysight.com

Jerry Yeoh ewe-keng_yeoh@keysight.com

Table 1 Serial Numbers

Model	Serial Number	Battery Serial Number
N9937B	MY59221067	C0001176
N9937B	MY59221082	C0001178
N9937B	MY59221212	C0001459

Table 2 Parts Required

Description	Qty	Part Number
Battery-Rechargeable Li-Ion 10.8V 6400mAh	1	1420-0937

Revision History:

Date	Service Note Revision	Author	Reason for Change	
01 Jun 2020	01	Yeoh Ewe-Keng (Jerry)	As Published	