Modification Recommended Service Note

Supersedes: NONE

N9938B FieldFox Handheld Microwave Spectrum Analyzer, 26.5 GHz

Serial Numbers: MY59221036, MY59221177, MY59221252

The Problem - The battery may go into Sleep mode after a short period of inactivity. Refer to www.keysight.com and the Contact Keysight link.

Parts Required:

P/N Description Qty.

Battery-Rechargeable Li-Ion 10.8V 6400mAh 1420-0937 1pc

ADMINISTRATIVE INFORMATION

ACTION		STANDARDS
CATEGORY:	X AGREEABLE TIME	LABOR: 0.5 Hours
LOCATION CATEGORY:	X SERVICE CENTER	SERVICE: USED INVENTORY: X SCRAP PARTS: X SCRAP
AVAILABILITY	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 30-June-2022
	X Calibration NOT Required	PRODUCT LINE: PLWN AUTHOR: JY
ADDITIONAL I	NFORMATION:	



Affects: N9913/4/5/6/7/8B and N9933/4/5/6/7/8B



Situation:

The battery may go into Sleep mode after a short period of inactivity. Battery replacement needed. Solution/Action:

1. Open the battery door and remove the battery from Fieldfox unit.



- 2. Check the serial number of the battery. Refer to the serial number list below.
- 3. If the battery serial number match the list of serial number below. Please order a new replacement battery (P/N: 1420-0937) from stock. Properly scrap the used battery.

If the battery serial number not in the list below. No replacement needed.

If the Fieldfox unit doesn't come with a battery. No replacement needed.



If you have any questions about this process, please contact: Christopher Rich christopher_rich@keysight.com

Christopher Rich
Jerry Yeoh

christopher_rich@keysight.com
ewe-keng_yeoh@keysight.com

Table 1 Serial Numbers

Model	Serial Number	Battery Serial Number
N9938B	MY59221036	C0001166
N9938B	MY59221177	C0001335
N9938B	MY59221252	C0001447

Table 2 Parts Required

Description	Qty	Part Number
Battery-Rechargeable Li-Ion 10.8V 6400mAh	1	1420-0937

Revision History:

Date	Service Note Revision	Author	Reason for Change	
01 Jun 2020	01	Yeoh Ewe-Keng (Jerry)	As Published	