

U1242B-02

# Information Only Service Note

Supersedes:  
NONE

## U1240B Series 4 Digit Handheld Multimeters

Serial Numbers: MY62070001 / MY99999999

**The Problem** – Changes on display backlight color

### Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

### ADMINISTRATIVE INFORMATION

Calibration Required  
 Calibration NOT Required

PRODUCT LINE: GM  
AUTHOR: ET

ADDITIONAL INFORMATION:

**Situation:**

Starting from MY62070001, the U124xB meter will have a new backlight color (Color index: 600nm). There are no changes to the brightness and the functionality of the display.  
\*Color index is defined by wavelength (nm)

Here is a comparison on how the meter look like before and after changing to the new backlight color (color index: 600nm).



Left: New backlight color (600nm)  
Right: Original backlight color (598nm)

**Solution/Action:**

No action required.  
Starting from MY62070001, all U124xB meter will have display with backlight color index: 600nm.

**Revision History:**

Date	Service Note Revision	Author	Reason for Change
27 June 2022	01	EhsTher	As Published