

U1251B-08

Information Only Service Note

Supersedes:
NONE

U1250 Series 4.5 Digit Handheld Multimeters

Serial Numbers: MY62070001 / MY99999999

The Problem – Changes on display backlight color

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: GM
AUTHOR: ET

ADDITIONAL INFORMATION:

Situation:

Starting from MY62070001, the U125xB meter will have a new backlight color (Color index: 600nm). There are no changes to the brightness and the functionality of the display.
*Color index is defined by wavelength (nm)

Here is a comparison on how the meter look like before and after changing to the new backlight color (color index: 600nm)



Left: New backlight color (600nm)
Right: Original backlight color (598nm)

Solution/Action:

No action required.

Starting from MY62070001, all U125xB meter will have display with backlight color index: 600nm.

Revision History:

Date	Service Note Revision	Author	Reason for Change
27 June 2022	01	EhsTher	As Published

