

U1560A-01

Information Only Service Note

Supersedes:
NONE

U1560A Passive Probe, 1:1, 45MHz, 1.2m

Serial Numbers: ALL

The Problem – The immediate replacement for U1560A.

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: GM
AUTHOR: WY

ADDITIONAL INFORMATION:

Situation:

U1560A will not be updated to the latest safety and regulatory requirements. Hence, starting from 1st Dec 2021, U1560A passive probe is no longer available for sale. The immediate replacement is U1560B passive probe which offers enhanced performance, a larger bandwidth and a higher safety rating.

Solution/Action:

Any defective U1560A passive probe within its warranty period will be exchanged with U1560B passive probe.

Revision History:

Date	Service Note Revision	Author	Reason for Change
29 Nov 2021	01	WanYee	As Published