

U1562A-01

# Information Only Service Note

Supersedes:  
NONE

## U1562A Passive Probe, 100:1, 300 MHz, 1.2m

Serial Numbers: ALL

**The Problem** – The immediate replacement for U1562A.

### Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

### ADMINISTRATIVE INFORMATION

---

Calibration Required  
 Calibration NOT Required

PRODUCT LINE: GM  
AUTHOR: WY

---

ADDITIONAL INFORMATION:

---

**Situation:**

U1562A will not be updated to the latest safety and regulatory requirements. Hence, starting from 1<sup>st</sup> Dec 2021, U1562A passive probe is no longer available for sale. The immediate replacement is U1562B passive probe which offers enhanced performance, a larger bandwidth and a higher safety rating.

**Solution/Action:**

Any defective U1562A passive probe within its warranty period will be exchanged with U1562B passive probe.

**Revision History:**

Date	Service Note Revision	Author	Reason for Change
29 Nov 2021	01	WanYee	As Published