

U1583B-01

Information Only Service Note

Supersedes:
NONE

U1583B AC Current Clamp

Serial Numbers: ALL

The Problem – U1583B now offers Certificate of Calibration (CoC)

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: GM
AUTHOR: WY

ADDITIONAL INFORMATION:

Situation:

Starting from 1st June 2021, Certificate of Calibration (CoC) will be provided for all U1583B shipment. Factory Test Certificate (FTC) is no longer provided along with U1583B shipment.

Solution/Action:

No action required.

For units shipped a year before 1st June 2021(refer to the list below), you can also obtain the Certificate of Calibration (CoC) from Keysight.com.

MY60270019	MY60470008	MY61160005
MY60460001	MY60470009	MY61160006
MY60460002	MY60470010	MY61160007
MY60460003	MY60490001	MY61170001
MY60460004	MY61030001	MY61170002
MY60460005	MY61060001	MY61190001
MY60470001	MY61060002	MY61190002
MY60470002	MY61060003	MY61190003
MY60470003	MY61120001	
MY60470004	MY61160001	
MY60470005	MY61160002	
MY60470006	MY61160003	
MY60470007	MY61160004	

Revision History:

Date	Service Note Revision	Author	Reason for Change
14 Dec 2021	01	WanYee	As Published