

U3606A-03

Information Only Service Note

Supersedes:
NONE

U3606A Multimeter | Power Supply

Serial Numbers: "ALL units"

The Problem -- U3606A(U3606-66001) will be replaced by U3606B(U3606-66003)

Parts Required:

P/N	Description	Qty.
U3606-66003	Multimeter Power Supply	1

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: GM
AUTHOR: KT

ADDITIONAL INFORMATION:

Situation:

U3606A Multimeter|DC Power Supply has been discontinued on June 1, 2014. In conjunction with this discontinued, U3606B(U3606-66003) has been identify as a replacement for U3606A(U3606-66001).

The U3606B Multimeter|DC Power Supply is available, giving added accuracy, improved resolution and test efficiency. Please refer to the following link as below for the comparison U3606A vs U3606B.
<http://literature.cdn.keysight.com/litweb/pdf/5991-4383EN.pdf?id=2458738>

In the event that U3606A require necessary repair, U3606B will be the replacement.

Solution/Action:

Please contact your nearest Keysight service center and send U3606A(U3606-66001) for the U3606B(U3606-66003) replacement if you observed the situation as mentioned above.

Revision History:

Date	Service Note Revision	Author	Reason for Change
12 Dec 2016	01	KT	As Published