

U3810A-01

# Information Only Service Note

Supersedes:  
NONE

## U3810A Advanced IoT Training Kit

Serial Numbers: ALL

U3810A must be separated from the controller module before servicing

### Parts Required:

P/N	Description	Qty.
-----	-------------	------

None

---

### ADMINISTRATIVE INFORMATION

Calibration Required  
 Calibration NOT Required

PRODUCT LINE: GM  
AUTHOR: CD

---

ADDITIONAL INFORMATION:

---

**Situation:**

The U3810A Advanced IoT Training Kit must be separated from the controller module before servicing.

**Solution/Action:**

The U3810A Advanced IoT Training Kit is controlled by a mini computer that must be removed before servicing the U3810A. Remove the U3810A from the platform, remove the controller module and set it aside. Reinstall the U3810A on the platform before shipment.

The procedure is documented at <https://www.keysight.com/find/AdvancedIoT> as both written instructions and a video demonstration.

**Revision History:**

Date	Service Note Revision	Author	Reason for Change
16 Jun 2020	01	Cheryl Diller	As Published