# 1147A-01 S E R V I C E N O T E

Supersedes: None

## 1147A 50 MHz/15A AC/DC Current Probe

Serial Numbers: ALL


The 1147A has been discontinued and replaced by the 1147B. It is in support until Sept 1, 2018. If there are any support needs for the 1147A, then use the 1147B product.

Parts Required:<br/>P/NDescriptionQty.1147B-FGCurrent Probe - 50 MHz/15A AC/DC 1

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
INFORMATION ONLY			
[[]] Calibration Required	PRODUCT LINE: 1A		
X Calibration NOT Required	AUTHOR: MR		
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2013 PRINTED IN U.S.A.





#### Situation:

The 1147A has been discontinued and replaced by the 1147B. It is in support until Sept 1, 2018.

#### Solution/Action:

If there are any support needs for the 1147A, then use the 1147B product

#### **Revision History:**

Revision Number	Date	Author	Reason For Change
1.0			As published