

33622A-05

# Information Only Service Note

Supersedes:  
NONE

## 33622A Waveform Generator, 120MHz, 2 Channels

Serial Numbers: ALL

**The Problem** – Option 336IQPU is no longer available.

### Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

### ADMINISTRATIVE INFORMATION

---

Calibration Required  
 Calibration NOT Required

PRODUCT LINE: GM  
AUTHOR: WY

---

ADDITIONAL INFORMATION:

---

**Situation:**

IQ baseband signal player (IQP) option is now enabled as standard feature in 33612A and 33622A function generators.

**Solution/Action:**

All installed base and new customers can enjoy this feature for free by upgrading their instrument (33612A/33622A) firmware to version 2.00 or above.

- Upgrading instrument without option IQP previously installed to firmware version 2.0 will show the option as “Included” in the System > Help > About window.
- Upgrading instrument with option IQP previously installed to version 2.0 will continue to show option IQP as installed.

There is no change in the functionality. All other license options must be purchased.

**Revision History:**

Date	Service Note Revision	Author	Reason for Change
03 Aug 2020	01	WanYee	As Published