S E R V I C E N O T E

SUPERSEDES: None

346C Noise Source

Serial Numbers: 0000A00000 / 9999Z99999

SWR failure at high end

Situation:

The 346C K01 is a 50 GHz noise source. There have been problems meeting the current SWR spec of 1.35 from 20-26.5 GHz.

Solution / Action:

The spec is being changed.

1-26.5 GHz 1.35 26.5-50 GHz 1.50

New spec: 1-20 GHz 1.35

20-26.5 GHz 1.40 26.5-50 GHz 1.50

DATE: March 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY