

34924A-02

Information Only Service Note

Supersedes:
NONE

34924A 70-Channel Reed Multiplexer for 34980A

Serial Numbers: ALL

The Problem – New Keysight Color

Parts Required:

P/N	Description	Qty.
34924-60001	70-Channel Reed Multiplexer new replacement module	1
34924-66001	Reed Multiplexer,70-Channel new replacement module (Rebranded)	1

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: PLGM
AUTHOR: SL

ADDITIONAL INFORMATION:

Situation:

The outlook of the instrument is experiencing a color change to comply with the new Keysight product color scheme. The redesigned 34924A provides the same product performance, specifications, and is 100% compatible with the existing 34924A.

Solution/Action:

Keysight customers:

No action is needed.

Keysight service centers:

For new unit replacement below MY56480461, use the part number 34924-60001 (Reed Multiplexer, 70-Channel). These parts are available as UTG. Once the parts are depleted, use the rebranded part numbers 34924-66001 (Reed Multiplexer, 70-Channel rebranded).

For new unit replacement of MY56480461 and above, use directly the rebranded part numbers 34924-66001 (Reed Multiplexer, 70-Channel rebranded).

Revision History:

Date	Service Note Revision	Author	Reason for Change
13 Feb 2020	01	SL	As Published