34937A-04

Information Only Service Note

Supersedes: NONE

34937A 32-Channel FormC/Form A General Purpose Switch for 34980A

Serial Numbers: MY62120001/ MY99999999

SG62120001/SG99999999

The Problem – New Orbital Sanded Covers for 34980A modules

Parts Required:

N/A

ADMINISTRATIVE INFORMATION

[]] Calibration Required[X] Calibration NOT Required

PRODUCT LINE: PLGM AUTHOR: MS

ADDITIONAL INFORMATION:



Situation:

34937A modules beginning with serial numbers MY62120001/SG62120001 or greater, will have new furnishings that have orbital sanded covers to avoid roller marks on the material. Refer to image 1 below:



Image 1: New Furnishing with Orbital Sanding

34937A modules with serial numbers less than MY62120001/SG62120001 will have glossy surfaces as shown in image 2.



Image 2: Old Furnishing with Glossy Surface

These changes have no impact on the module's performance.

Solution/Action:

No Action is needed.

Revision History:

Date	Service Note Revision	Author	Reason for Change	
28 June 2022	04	MS	As Published	