

S E R V I C E N O T E

SUPERSEDES: None

HP 37701A T1 Tester

Serial Numbers: 0000U00000 / 3127U00400

Additional Features can be retrofitted to older instruments.

Situation

Instruments with serial numbers above 3127U00400 have additional features - Restart capability, Longer User Word and All Signalling Bits display.

These features can be retrofitted to earlier instruments by ordering an upgrade kit.

Solution/Action:

Order retrofit kit HP part number 37701-60046.

Kit Contents:

- Hardware parts
- Retrofit Instructions
- Replacement Operating and Calibration Manual
- Datacom Module Manual Update information - required only for HP 37701A's which have had Datacom Lid Modules added.

DATE: 02 August 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:	AGREEABLE TIME	<input checked="" type="checkbox"/> PERFORMANCE ENHANCEMENT <input type="checkbox"/> SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> HP LOCATION	AVAILABLE UNTIL:
AUTHOR: ER	ENTITY: 1400	ADDITIONAL INFORMATION: