

Supersedes:
None**HP MODEL 5345A ELECTRONIC COUNTER****All Serial Prefixes****ROM PART NUMBER CHANGES**

Three revisions have been made on the A15 assembly due to ROM changes (U8, U16, U24, U32). A different A14 assembly is used with each A15 assembly revision. The following table lists each A14/A15 assembly combination and new ROM part numbers for each revision.

Also included in the table are new ROM part numbers for the A12 HP-IB assemblies.

A15 Assembly	A14 Assembly Used With	Reference Designator	Original P/N	Replaced by P/N
05345-60045	05345-60044	U8	1816-1018	05345-80020
		U16	1816-1019	05345-80021
		U24	1816-1020	05345-80022
		U32	1816-1021	05345-80004
05345-60035	05345-60034	U8	1816-0824	05345-80012
		U16	1816-0825	05345-80013
		U24	1816-0826	05345-80014
		U32	1816-0827	05345-80015
05345-60015	05345-60014	U8	1816-0344	05345-80007
		U16	1816-0345	05345-80008
		U24	1816-0346	05345-80009
		U32	1816-0347	05345-80010

A12 Assembly	Reference Designator	Original P/N	Replaced by P/N
05345-60018	U29	1816-0254	05345-80005
	U27	1816-0255	05345-80006
05345-60021	U44	1816-0254	05345-80005
	U52	1816-0255	05345-80006
	U4	1816-0413	05345-80011
05345-60023	U17	1816-0254	05345-80005
	U16	1816-0255	05345-80006

I/NS/-WN

9/81-02/DD



For more information contact a local Hewlett-Packard Office. (Hewlett-Packard has 200 Sales and Service Offices in 75 countries). Or write: Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94304, U.S.A.

Printed in U.S.A.

