

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**6671A-06B**

# S E R V I C E N O T E

Supersedes:  
6671A-06A

## 6671A 2KW General Purpose System Power Supply

Serial Numbers: 3624A-00578 / 9999Z99999

### Front Panel Parts List

#### Situation:

When damage occurs to the front panel portion of the power supply, several replacement parts may be required to repair the instrument.

#### Solution:

This is a parts list for convenience that lists the commonly replaced front panel parts.

Units with earlier serial numbers, that need new optical encoders must also order a new “**Tested Keypad PCA**” p/n **5060-3400**, which includes 2 knobs.

**5064-0125 / 5064-0126** ASSY-FR PNL, SERVICE KIT is Obsolete, and is no longer available.

#### Front Panel Parts Required:

<u>Part Number</u>	<u>Quantity</u>	<u>Description</u>
0370-3238	2	KNOB 6mm
0515-0374	2	SCR-MACHINE
0515-2535	1	SCREW-METRIC
0960-0912	2	ENCODER-ROTARY
1000-0842	1	WINDOW
5001-0539	2	TRIM SIDES, FRONT GRAY
5001-6748	1	FRONT PANEL (Overlay)
5040-1735	1	KEYPAD

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR: RJM      PRODUCT LINE: 33

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002  
PRINTED IN U.S.A.



June 28, 2002

06671-80001 1  
5040-1703 1

NAMEPLATE  
FRONT FRAME