# 81680A-02

# <u>SERVICE NOTE</u>

Supersedes: NONE

81680A – Tunable Laser Module, Low SSE, 1550 nm

**Serial Numbers:** [0000A00000 / 9999Z99999]

# Product is out of support - Upgrade to actual 81600B available

Parts Required: P/N	Description	Qty.
81600B #UG5	Upgrade to 81600B #160	1ea
or		
81600B #UG6	Upgrade to 81600B #150	1ea
or		
81600B #UG7	Upgrade to 81600B #201	1ea

## ADMINISTRATIVE INFORMATION

SERVICE NOTE	CLASSIFICATION:	
INFORMATION ONLY		
AUTHOR: JM	PRODUCT LINE: 3E	
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2007 PRINTED IN U.S.A.



September 12, 2007

Page 2 of 2 81680A-02

#### **Situation:**

The product is beyond its support life, so it is out of support and repairs are no longer available.

#### **Solution/Action:**

For customer satisfaction Agilent is offering the following upgrades to the actual 81600B Tunable Laser Source.

- Please order product **81600B** #UG5 for an upgrade from TLS series 81640A/B or 81680A/B to **81600B** #160.
- Please order product **81600B** #UG6 for an upgrade from TLS series 81640A/B or 81680A/B to **81600B** #150.
- Please order product 81600B #UG7 for an upgrade from any TLS series 81xx0A/B or 816x2A/B to 81600B #201.

Specifications for the individual 81600B options can be found in the 81600B User's Guide on the Agilent Internet.

For ordering the 81600B #UGx upgrade please contact the Agilent sales representative.

### For Agilent Service Center

Please pass the customer information to the Agilent sales organization.