

S E R V I C E N O T E

SUPERSEDES: NONE

85025A Detector**Serial Numbers:** 5767 thru 5778 or 5785 and above**Duplicate Service Notes:**

85025A-03

85025B-02

85025E-02

Current detectors do NOT require adjustments as documented in the March 1988 manual.**Situation:**

85025A detectors specified above do not require adjustments. These newer detectors have been so labeled.

Solution/Action:

Before adjusting a 85025A detector, determine whether the adjustment is required: read its label or compare its serial number to the above numbers.

DATE: 16 September 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

DL

ENTITY:

5300

ADDITIONAL INFORMATION: