

Information Only Service Note

Supersedes: NONE

85130C Test Port Adapter, 3.5 mm (Test Port) to Type-N

Serial Numbers: ALL

There has been a pin depth specification change for the 85054-60029 and 85054-60030 adapters as per the table below. This change was made to improve the electrical transmission performance and repeatability of the adapter.

This Service Note only highlights the specification changes in the standard calibration process.

Parts Required: NONE

ADMINISTRATIVE INFORMATION

Calibration NOT Required

PRODUCT LINE: PLWN AUTHOR: KS

ADDITIONAL INFORMATION: Models affected: 85130C, 85130D, 85130F, and 85130G



Situation:

There has been a pin depth specification change for the 85054-60029 and 85054-60030 adapters as per the table below. This change was made to improve the electrical transmission performance and repeatability of the adapter.

Solution/Action:

On incoming inspection, Keysight will pass all devices which meet either specification and will ensure all devices meet the new specification when they are returned.

	Old Spec	cification	New Spe	cification
Connector	Allowable Recession		Allowable Recession	
	mm	in	mm	in
NMD-3.5mm female	-0.000 to -0.056	-0.000 to -0.0022	-0.015 to -0.056	-0.0006 to -0.0022
Type N-female	+5.2451 to +5.2578	+0.2065 to +0.2070	+5.23494 to +5.2451	+0.2061 to +0.2065
Type N-male	-5.2578 to -5.2705	-0.2070 to -0.2075	-5.2705 to -5.28066	-0.2075 to -0.2079

Revision History:

Date	Service Note Revision	Author	Reason for Change
260ct2015	01	Keith Stengl	As Published