S E R V I C E N O T E

SUPERSEDES: NONE

85301B Antenna measurement system, 2 to 20 GHz

Serial Numbers: 0000000000 / 99999999

Performance Software

To Be Performed By: Customer

Parts Required: 08511-60024

Situation:

The older performance software p/n. 85309-10001 is no longer avialable. It has been replaced with 08511-60024

Solution/Action:

Order 8511A/B and Antenna software (p/n. 08511-60024) for the performance verification.

DATE: November 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

MODIFICATION RECOMMENDED

ACTION CATEGORY:	IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME	STANDARDS: LABOR 1.0 Hours			
LOCATION CATEGORY:	CUSTOMER INSTALLABLE ON-SITE SERVICE CENTER	SERVICE INVENTORY:	RETURN SCRAP SEE TEXT	USED PARTS:	RETURN SCRAP SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: PRODUCT'S SUPPORT LIFE			
AUTHOR: SP	ENTITY: 5300	ADDITIONAL INI	FORMATION:		

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

