

S E R V I C E N O T E

SUPERSEDES: NONE

**8648C Signal Generators
(Option 1E6 (Pulse Modulation) only)**

Serial Numbers: 0000A00000 / 9999Z99999

8648 Pulse Modulation Operation**Situation:**

Many 8648 pulse modulation option signal generators are being returned for repair with the fault "NO RF OUTPUT", when there is in fact nothing wrong with the units.

It turns out that the Pulse Modulation has not been turned off.

Solution/Action:

Powering the signal generator on and off will not reset the Pulse Modulation to a default state. After use, the Pulse Modulation should be turned off by going into Pulse Modulation mode (by pressing the AM key twice) and then switching the Modulation On/off key to off.

DATE: October 1995

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: EV	ENTITY: E600	ADDITIONAL INFORMATION:
-------------------	---------------------	-------------------------