POINDEXTER, BILL

SERVICE NOTE

SUPERSEDES:

None

HP MODEL 8690A SWEEP OSCILLATOR

All Serial Numbers

REPLACEMENT OF CAPACITORS CONTAINING PCB

Capacitors C2 and C3 in all 8690A's contain Polychlorinated Biphenyls (PCB) as a dielectric. PCB has been classified as a health hazard by the Environmental Protection Agency.

The recommended replacement for C2 and C3 is HP Part Number 0160-0669. The 0160-0669 has the same capacitance value and voltage rating as the old capacitors containing PCB and is a direct replacement.

No recalibration is necessary.

Correct your 8690A Operating and Service Manual Parts List to reflect the above change.

AS/mh/WN

2/73-4

