

DSO3062A-02

S E R V I C E N O T E

Supersedes:
NONE

DSO3062A - Oscilloscope, 1GSa/s, 2-channel, 60 MHz

Serial Numbers: ALL

The 3000 series is not being manufactured anymore. We are facing a depletion of this specific model and it needs to be replaced by a 1000 series scope.

Parts Required:

P/N	Description	Qty.
DSO1002A-FG	Oscilloscope 2Ch, 60MHz	1
54125-69801	60 MHz 2Ch Oscilloscope-Exch.	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY INTERNAL ONLY DOCUMENT	
AUTHOR: EG	PRODUCT LINE: PL1A
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2011
PRINTED IN U.S.A.

February 2, 2011

Rev. 18



Situation:

The DSO3062A is not being manufactured any longer and the Service Centers are running into a depletion state.

Solution/Action:

The DSO3062A needs to be replaced by the DSO1002A with the exception when the customer is using GPIB as the main communication means for their critical measurements. In this specific case another suitable 3000 series should replace it.