## **DSO3202A-01**

# <u>SERVICE NOTE</u>

Supersedes: NONE

DSO3202A - Oscilloscope, 1GSa/s, 2-channel, 200 MHz

**Serial Numbers: ALL** 

The 3000 series is not being manufactured anymore. We are facing a depletion of this specific model and it needs to be replaced by a 1000 series scope.

#### ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: |                    |
|------------------------------|--------------------|
| INFORMATION ONLY             |                    |
| AUTHOR: EG                   | PRODUCT LINE: PL1A |
| ADDITIONAL INFORMATION:      |                    |
|                              |                    |

© AGILENT TECHNOLOGIES, INC. 2011 PRINTED IN U.S.A.



February 11, 2011

Rev. 18

Page 2 of 2 DSO3202A-01

#### **Situation:**

The DSO3202A is not being manufactured any longer and the Service Centers are running into a depletion state.

### **Solution/Action:**

The DSO3202A needs to be replaced by the DSO1022A with the exception when the customer is using GPIB as the main communication means for their critical measurements. In this specific case another suitable 3000 series should replace it.