

E3649A-05

S E R V I C E N O T E

Supersedes:
N/A

E3649A DC Power Supply

Serial Numbers: MY53186001 to MY99999999

New Error Message

Parts Required:

P/N	Description	Qty.
N/A		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
<input type="checkbox"/> Calibration Required	PRODUCT LINE: WC
<input checked="" type="checkbox"/> Calibration NOT Required	AUTHOR: TL
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2013
PRINTED IN U.S.A.

July 12, 2013
Rev. 21



Situation:

There are some new error messages for E3649A power supply starting from serial number MY53186001 as shown in Table 1 below.

114	Header suffix out of range
120	Numeric data error
130	Suffix error
503	SPI data error
609	System ADC test failed

Table 1, new error messages list

Solution/Action:

Refer E3649A [User's and Service Guide](#) Chapter 4 Error Messages for more details.

Revision History:

Revision Number	Date	Author	Reason For Change
1.0		TL	As published