

E4356A-03

S E R V I C E N O T E

Supersedes:
NONE

E4356A 2000 Watt GPIB Power Supply

Serial Numbers: 0000A0000 – MY42000417

Discontinued LCD and PCA compatibility

Situation:

The LCD p/n 5063-3473 is no longer available. The discontinued LCD p/n 5063-3473 has been replaced by LCD p/n 5065-7075. When replacing LCD 5063-3473 with LCD 5065-7075 the front panel PC assembly also has to be replaced with tested front panel PC assembly p/n E4356-61023 with ROM 5081-4989 Rev. A.03.00.

Front panel PC assembly p/n E4356-61023 with ROM 5081-4989 Rev A.03.00 is NOT compatible with LCD p/n 5063-3473.

Note: When replacing the front panel assembly the unit will need to be initialized and re-calibrated.

Available Front Panel Parts:

| P/N | Description | Qty. |
|------------|--------------------|-------------|
| 5040-1735 | Keypad | 1 |
| 5065-7075 | LCD | 1 |
| 5080-2261 | LCD Cable | 1 |

ADMINISTRATIVE INFORMATION

| |
|---|
| SERVICE NOTE CLASSIFICATION: INFORMATION ONLY |
| AUTHOR: BH PRODUCT LINE: SP |
| ADDITIONAL INFORMATION: |

