

# E4402B-16A

# S E R V I C E N O T E

Supersedes:  
E4402B-16

## E4402B ESA Series Spectrum Analyzer

**Serial Numbers:** All

### **A8A1 RF Assembly Replacement Part Numbers**

**Parts Required:**

P/N	Description	Qty.
None		

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR: D.C.    PRODUCT LINE: 12

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2007  
PRINTED IN U.S.A.



July 4, 2007

**Situation:**

Until recently, there were a couple of different part numbers for the ESA RF assembly. As a reference from the service note E4402B-16, the table used for the RF assembly replacement until now was as below:

Serial Prefix		Option 1D5	ASA1 Part Number
From	Through		
MY0000 / US0000 / SG0000	MY4420 / US4420 / SG4420	No	E4403-69073 <sup>1</sup>
		Yes	E4403-69074 <sup>1</sup>
MY4421 / US4421 / SG4421	MY4509 / US4509 / SG4509	No	E4403-69074 <sup>1</sup>
		Yes	E4403-69074 <sup>1</sup>
MY4510 / US4510 / SG4510	MY9999 / US9999 / SG9999	No	E4403-60080 <sup>2</sup>
		Yes	E4403-60080 <sup>2</sup>

<sup>1</sup> The new part is no longer available so this exchange assembly will need to be used.

<sup>2</sup> There is also an exchange assembly available for this part (E4403-69080).

In the recent past, there was a reliability improvement done on the ESA RF assembly. The new RF assembly has the part number E4403-60087 and it's exchange is E4403-69087. As a result of this reliability improvement, the older part numbers for the ESA RF assembly are no longer available. Now there are is only one part number available for the RF assembly, E4403-60087 and it's exchange assembly E4403-69087. Due to the higher reliability of the E4430-60087, there will be less failures and the availability of exchange assembly E4403-69087 is not guaranteed.

**Solution/Action:**

1. Order E4403-69087 or E4403-60087 for all ESA series analyzers (except E4401B and E4411B), irrespective of the model number and the option configuration of the unit.
2. Due to the higher reliability of the E4430-60087, there will be less failures and the availability of exchange assembly E4403-69087 is not guaranteed. **If E4403-69087 is not available, please order E4403-60087.**