E4438C-15A S E R V I C E N O T E

Supersedes: E4438C-15

E4438C

Serial Numbers: [0000A00000 / 9999Z99999]

Customers with E4438C's with failing Hard disk drives E4400-60253 are eligible to have their product repaired at Agilent's expense until 1NOV2007.

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

P/N Description Qty.

E4400-60253 Hard disk Drive 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION		[]] PERFORMANCE ENHANCEMENT
CATEGORY:	On Specific failure	X SERVICE / RELIABILITY ENHANCEMENT
LOCATION	[[]] CUSTOMER INSTALLABLE	AVAILABILTY:
CATEGORY:	X ON-SITE X SERVICE CENTER	1 Nov 2007
AUTHOR: HLU	PRODUCT LINE: 15	
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2007 PRINTED IN U.S.A.



Page 2 of 2 E4438C-15A

Situation:

Customers with E4438C's with failing Hard disk drives, E4400-60253, are eligible to have their product repaired as described in "Solution/Action" section of this Service Note at Agilent's expense until 1NOV2007.

Solution/Action:

Replace failed hard disk drive assembly E4400-60253 as required.