

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

E4446A-08

S E R V I C E N O T E

Supersedes:
None

PSA Series Spectrum Analyzer E4440A, E4443A, E4445A,
E4446A, E4448A

Serial Numbers: [0000A00000 / 9999Z99999]

**Please run the Frequency Response Adjustment (All Bands) after replacing the
A10 Third Converter Assembly.**

Parts Required:

P/N	Description	Qty.
NONE		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: BNN PRODUCT LINE: 12

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2004
PRINTED IN U.S.A.



April 13, 2004

Situation:

The PSA may fail frequency the frequency response test after replacing the A10 Third Converter assembly.

Solution/Action:

Please run the Frequency Response Adjustment(All Bands) after replacing the A10 third converter.