

Information Only Service Note

Supersedes: E4980A-10

E4980A Precision LCR Meter 20 Hz to 2 MHz

Serial Numbers: ALL

Manufacturing ID Number: N/A

LCD Display Part Number Change

Parts Required:

P/N Description Qty.

2090-1101 LCD Display 3.8 inch 1 0950-5724 DC-DC LED Module converter (Inverter) 1

ADMINISTRATIVE INFORMATION

[[]] Calibration Required PRODUCT LINE: WN
[X] Calibration NOT Required AUTHOR: jm

ADDITIONAL INFORMATION:

This service note communicates the updated E4980A LCD Part number and the part dependency on both LCD and DC-DC LED converter (inverter).

Situation:

Due to the lack of compatibility on both generation of LCD display and inverter, old LCD display and inverter should not be mixed and used with new LCD Display and LCD inverter.

Solution/Action:

- 1. Replace BOTH Old LCD and inverter when either one of the two old parts is defective in ensuring compatibility.
- 2. Update the firmware to the stated revision in Table 1-1.

Refer to the table 1-1 for details.

Table 1-1

	OLD (Sharp)	NEW (Kyocera)
LCD	5012-8830	2090-1101
	(2090-0825)	
Backlight inverter	0950-4111	0950-5724
E4980A Firmware	Update to A.06.12 (*1)	Update to A.06.13 ^(*2)
Installed Firmware	A.01.00 to A.06.10	A.06.11

NOTE:

- (*1) Do not install FW A.06.11 or A.06.13 on existing E4980A with OLD (Sharp) LCD display. Unit with OLD (Sharp) LCD display would be fitted with FW Rev. A.06.10 or A.06.12.
- (*2) Do not install FW A.06.12, A.06.10 or earlier on existing E4980A with NEW (Kyocera) LCD display. Unit with NEW (Kyocera) LCD display would be fitted with FW Rev. A.06.11 or A.06.13.

Revision History:

Date	Service Note Revision	Author	Reason for Change
E4980A-10	14 Apr 2015	ls	As published
E4980A-10A	01 Oct 2015	jm	Update FW info

