

E5071C-07

S E R V I C E N O T E

Supersedes:
NONE

E5071C - ENA Series Network Analyzer, 9 kHz to 20 GHz

Serial Numbers: ALL

Firmware update information

Parts Required:

P/N	Description	Qty.
E5071-82302	HDD Installed	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: jm	PRODUCT LINE: WN
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2010
PRINTED IN U.S.A.

August 24, 2010

Rev. 17



Situation:

E5071-82302 is the HDD of E5071C in which OS and firmware were installed.
Firmware Rev 09.50 has a bug that old state file cannot be recalled.

Solution/Action:

FW Rev. From	FW Rev. To	Reason
Rev. A.09.50	Rev. A.09.54 or later	Rev. A.09.50 has a bug that old state file cannot be recalled.

The latest firmware can be downloaded from the below pages.

[Agilent Internal web site]

http://kobemktg.jp.agilent.com/field_eng/service/firmware_history/fwhist_e5071c.htm

or

[Agilent External Web site]

<http://www.home.agilent.com/agilent/editorial.jsp?cc=US&lc=eng&ckey=879905&nid=-536902633.350794.02&id=879905>

How to check the Firmware Revision

- (1) When you can see the HDD itself, you can check the ID label. For Rev A.09.50 or earlier, there is no ID label attached to the HDD.



- (2) When the HDD is installed to the E5071C, you can check the firmware revision to click “System” and “Firmware Revision”.

- End of Document -