E8362C-02

<u>SERVICE NOTE</u>

Supersedes: NONE

E8362C PNA Microwave Network Analyzers

Serial Numbers: US00000000/US99999999 (ALL)

During System Verification test, E8362C analyzers that encounter errors while measuring the verification kit devices should upgrade to the most recent firmware and retry the test.

| Parts Required: | | |
|-----------------|-------------|-----|
| P/N | Description | Qty |

ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: | | |
|---|------------------|--|
| INFORMATION ONLY | | |
| AUTHOR: MF | PRODUCT LINE: WN | |
| ADDITIONAL INFORMATION: Affected PNA models: E8361/2/3/4C and N5230C. Service Note history: E8362C-02 written August 31, 2009. | | |

© AGILENT TECHNOLOGIES, INC. 2009 PRINTED IN U.S.A.



September 1, 2009

Rev. 16

NONE

Page 2 of 2 E8362C-02

Situation:

During System Verification test, some E8362C analyzers are experiencing errors while measuring the verification kit devices.

Solution/Action:

Download the most recent firmware and retry the test.