S E R V I C E N O T E

SUPERSEDES: None

E9070A 95000 High Speed Memory Tester

Serial Numbers: 0000A00000 / 9999Z99999

E9075-82011 HSI Tool Kit Assembly for 95000

To Be Performed By: Agilent-Qualified Personnel

Situation:

Access and repair of the CMD High Speed interface on the 95000 is extremely limited without the proper tools and spare parts.

Solution / Action:

The instruments included in the HSI tool kit provide for much easier accessibility, maintenance, and repair. The kit includes all the required wrenches and screwdrivers required, as well as spare pogo pins, connectors, and jumpers. Also included are spacers, release tools, sensor bypassers, and other tools needed for repairs and upgrades. The kit will be available through GSL for \$1300.00

DATE: November 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: ENTITY: ADDITIONAL INFORMATION:

BW 025Y

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

