J2522B-04

SERVICE NOTE

SUPERSEDES: None

J2522B LAN Advisor

Serial Numbers: EC Label 06 and 07

Upgrade F/W for Quantum 540 MB and 1.08 GB Hard Disk Drives

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

0950-3008 540 MB hard disk 0950-3072 1.08 GB hard disk

Situation:

The new Europa series hard disk from Quantum have an old version of the controller firmware installed. If the unit has an EC label with a code of 06 or 07 you need to run the hard disk upgrade software disk on the unit before returning it to the customer. The part number for the upgrade disk is 5011-2932, if you do not have this disk contact CCO support or download the software from Colorado's ftp node (Contact Ron Mallette for details). These files are available on WEB site http://www-cco.col.agilent.com under R&D Archives. Copy all files to a formatted bootable floppy disk, the files are in directory pub/mtksupport/harddrv on both the ftp or WEB site methods.

Solution/Action:

Load the hard disk upgrade software on all J2522B with an EC code of 06 or 07, by installing the floppy disk and power on the unit. Run Scandisk or Norton Disk Doctor on the media, if bad blocks are detected replace the hard disk drive.

DATE: June 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	 IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME 	STANDARDS: Labor 0.25 Hour
LOCATION CATEGORY:	 CUSTOMER INSTALLABLE ON-SITE SERVICE CENTER 	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: August 1998
AUTHOR: RM	ENTITY: 3801	ADDITIONAL INFORMATION:

© 1996 AGILENT TECHNOLOGIES
PRINTED IN U.S.A.

